

To: Clifford Firstenberg[cfirstenberg@tierrasolutionsinc.com]; Naranjo, Eugenia[Naranjo.Eugenia@epa.gov]; Franklin, Elizabeth A NWK[Elizabeth.A.Franklin@usace.army.mil]; AccardiDey, AmyMarie[aaccardidey@louisberger.com]
Cc: Brian Mikucki[bmikucki@tierrasolutionsinc.com]
From: Warner, Len
Sent: Wed 10/19/2016 6:13:05 PM
Subject: RE: Logistics update

Hi Cliff:

Did I ever specifically say that I was talking with ASI? I don't recall that I did...apparently some vibracoring contractors are sensitive about describing their atypical/less frequently used coring techniques in case someone should be incautious about how much sediment they try to collect at one time vs. the capacity of their winch and davit/A-frame.

That said, in response to your question:

When we add the barrels to the side of the main barrel attached to the head, there is NO check valve that we use. We rely heavily on the core catchers and only use this method for volume reasons and for specific projects. Also we consider the type of material we are trying to collect as it does work well for some sediments. We have tried a couple of things to try to use as valves but they just pop off or blow out upon collection.

Best regards, Len

Len Warner

Director | Environmental Evaluation & Forensics

Louis Berger | +1.914.798.3721 | louisberger.com

From: Clifford Firstenberg [mailto:cfirstenberg@tierrasolutionsinc.com]
Sent: Tuesday, October 18, 2016 1:01 PM

To: Naranjo, Eugenia <Naranjo.Eugenia@epa.gov>; Franklin, Elizabeth A NWK <Elizabeth.A.Franklin@usace.army.mil>; AccardiDey, AmyMarie <aaccardidey@louisberger.com>; Warner, Len <lwarner@louisberger.com>
Cc: Brian Mikucki <bmikucki@tierrasolutionsinc.com>
Subject: Logistics update
Importance: High

I spoke with Eugenia a few minutes ago and told her I would update the team on our conversation.

In pulling our inventory of excess core liner stored at Lister, it turns out it is 3 5/8 OD liner that we used with OSI's vibracorer. ARCADIS' vibracorer, however, needs a minimum 3 3/4 OD liner, so we just hit a brick wall as far as starting on Thursday. We are pursuing the following options:

1. Traditional approach: we are getting info on lead time to get new core liner and caps for the traditional approach of a single barrel core of nominal 4-inch diameter.
2. Multi-liner: based on Eugenia's email and info from ASI regarding multiple cores at one time, we may be able to take advantage of an overstock of 3-inch liner that ARCADIS has in Syracuse that we could use as described by ASI.

As the afternoon progresses, I will keep everyone updated.

Len – can you get more info from ASI about how they affix the valves at the top of the liners?

Thanks
Cliff

-

Clifford E. Firstenberg

Principal and Environmental Sciences Manager

Tierra Solutions, Inc.

E-mail: cfirstenberg@tierrasolutionsinc.com

Phone: ***New number: 757-282-6462 (757-258-7720 no longer in service)***

Cell: 757-206-6281



CONFIDENTIALITY NOTICE...

The information in this email may be confidential and/or privileged. This email is intended to be reviewed by only the individual or organization named above. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system.

Thank You.

This message, including any attachments hereto, may contain privileged and/or confidential information and is intended solely for the attention and use of the intended addressee(s). If you are not the intended addressee, you may neither use, copy, nor deliver to anyone this message or any of its attachments. In such case, you should immediately destroy this message and its attachments and kindly notify the sender by reply mail. Unless made by a

person with actual authority conferred by Louis Berger, the information and statements herein do not constitute a binding commitment or warranty by Louis Berger. Louis Berger assumes no responsibility for any misperceptions, errors or misunderstandings. You are urged to verify any information that is confusing and report any errors/concerns to us in writing.